

Attention Firearms Instructors

Date: 5/15/2007

Case #: 2007

Author ID: 081



Cracked Receiver and Locking Block



Cracked Receiver



Cracked Receiver and Locking Block

The Lyndhurst Police Department has recently had a failure to one of its Glock 32's. .357sig. While qualifying at the range an officer experienced a weapon malfunction and difficulty dropping the magazine. Upon closer inspection of the weapon it showed that the Receiver was completely cracked through, from the locking block pin hole up to the top of the receiver. On the inside of the receiver the locking block pin was sheared and the internal part of the receiver is bent.

These weapons have been in service since April of 2000. If there are any other departments that has experinced anything similar to this please contact Captain Cinardo at 201-939-2900 ext:253 or Sgt. Devlin at 201-939-2900 ext:273

Lyndhurst Twsp. Police Dept. - Headquarters
(201) 939-2900